## PERMFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/Institution)

Part-1

| 1.  | Name of the School                        | Mahant Lachhman Dass Sen. Sec. |
|-----|---|--------------------------------|
|     |   | School                         |
| 2.  | Location                                  | Talwandi Kalan                 |
| 3.  | Plot Area                                 | 11371.67 Sq. Meter             |
| 4.  | Plinth Area (GF+FF)                       | 3330 Sq. Meter                 |
| 5.  | Number of the Storeys                     | Three (Triple)                 |
| 6.  | Year of construction of the Building      | First Floor (2001-02)          |
|     |   | Second Floor (2006-07)         |
|     |   | Third Floor (2008-09)          |
|     | If the building has been construction the |                                |
| 7.  | Provision of the qualified engineer, the  |                                |
|     | following details may be given:-          |                                |
|     | a) Name of the Engineer with              | Iqwinderpal Singh Dhanoa       |
|     | Qualification.                            | B.Tech.                        |
|     | b) Address of the Engineer                | Talwandi Kalan                 |
|     | c) Set of the structural drawing used     | Attached                       |
|     | in the construction. If available         | Attached                       |
|     | d) Name and address of the Architect      | Satish Sharma                  |
|     | with qualification.                       | 81, Grain Market, Mullanpur    |
| 8.  | Whether the building has been             |                                |
|     | construction for the purpose.             |                                |
|     | a. School                                 | Yes                            |
|     | b. Residential purpose and covered        | No                             |
|     | for use as a school.                      |                                |
| 9.  | Materials used for roofs.                 |                                |
|     | a. RCC Slab.                              | Yes                            |
|     | b. R.S. Joists and battens                | No                             |
|     | c. Wooden joists and battens              | No                             |
| 10. | Materials used for walls                  | =                              |
|     | a. Mud mortar                             | No                             |
|     | b. Cement mortar                          | Yes                            |
| 11. | Flooring:-                                |                                |
|     | a. Conglomerate                           | Yes                            |
|     | b. Tarrazo                                | NO                             |
|     | c. Brick paving                           | No                             |
|     | A detailed drawing indicating dimensions  |                                |
| 12. | of the rooms along with size and location | Plan Attached                  |
|     | of floors and windows (attached).         | a bow                          |
|     |   | Principal                      |

Principal
Mahast Lucian T Sec
San all T
Annel T .0.10000000

## Part-II

## (TO BE FILLED BY THE SDE OF PWD B&R DEPTT.) <u>SCHOOL SAFETY CERTIFICATE</u>

Mahant Lachhman Dass Senior Secondary School Talwandi Kalan (Ldh.)

- a) I have visited the above mentioned school on 19-04-2024 and have visually inspected it from all angle of safety and I find it is fit for normal use as school building.
- b) In case and additional/alteration or expansion and modification to his building is—to be carried out, the same be carried out under the supervision of technically qualified engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is affected floor or if there is settlement of walls/foundations or safing of roofs etc. immediately inspection of the under signed be arranged to check the stability and safety of the building

d) This building can be safely occupied for normal use up to 31-03-2025 (for Year 2024-25)

(Indicate year u to which it can be used)

1000

Sub Divisional Engineer Construction Sub Division PWD (B&R) Jagreon at Ludviger

ਪਿੱਠ ਅੰਕਣ ਨੰ: 62-63

ਮਿਤੀ: 22/04/2024

- 1. ਉਪਰੋਕਤ ਸਕੂਲ ਦਾ ਇਸ ਦਵਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ ਅਤੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ਼ ਪਾਈ ਗਈ। ਇਸ ਲਈ ਸਾਲ 2024–25 ਦੌਰਾਨ ਮਿਤੀ 31.03.2025 ਤੱਕ ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫ਼ਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।
- 2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 1, ਲੋ:ਨਿ:ਵਿ:, ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

